

Storage and Handling Instructions for Window Films

Storage:

Must be kept dry at all times. Do

Not store on end

Recommended storage temperatures are from 40°F (4°C) to 100°F (38°C)

Do not store at temperatures over 140°F or below 32°F

Avoid impacting containers. If box is damaged, return to supplier

Handling:

Heavy Gauge polyester film will cause cuts

Cut resistant and static resistant gloves are recommended

As with most plastics, movement over metal rollers will produce static charges. Use caution when handling to prevent shocks.